

Give your hands a break with this job saving tool. The left side of this tool provides a cable center/dielectric guide function which insures proper alignment of cable into the F-connector. Excellent for use in cold weather when installers typically wear gloves.

The right side of this tool provides insertion assistance with RCA and BNC connectors. Both sides of this tool provides assistance with leverage while pressing the connector onto the coaxial cable. Some coaxial cable jackets are stiff, cold weather causes all jackets to be difficult, and the CGT-FBR helps in pressing the connector onto the cable.

FEATURES:

- **Helps with installation of connectors onto coaxial cable**
- **Works with F, RCA and BNC connectors**

Cable center/dielectric guide function which insures proper alignment of cable into the F-connector

Provides insertion assistance with RCA and BNC connectors



CGT-FBR


Insert the tip of our coax here after you slide the f-connector over the guide



HOLLAND
Electronics LLC **CGT-FBR**



F-Connector Installation Instructions



Hold the F Connector and CGT-FBR Tool in each hand



Insert the F connector onto the small end of the tool



Guide your stripped coax into the end of the small tube on tool
(This tube will guide your center conductor safely through connector)



Firmly press the cable, ensuring the connector is inserted entirely




The connector is ready to be terminated with the Compression Tool

HOLLAND
Electronics LLC **CGT-FBR**




BNC-Connector Installation Instructions



Hold the BNC Connector and CGT-FBR Tool in each hand



Insert the BNC connector into the large end of the tool



Guide your stripped coax into the end of the BNC connector



Firmly press the cable, ensuring the connector is inserted entirely



The connector is ready to be terminated with the Compression Tool

HOLLAND
Electronics LLC **CGT-FBR**




RCA-Connector Installation Instructions



Hold the RCA Connector and CGT-FBR Tool in each hand



Insert the RCA connector into the large end of the tool



Guide your stripped coax into the end of the RCA connector



Firmly press the cable, ensuring the connector is inserted entirely



The connector is ready to be terminated with the Compression Tool



Other Recommended Connector Tool Products by Holland Electronics

Compression Connector Tool
P/N: CT-FBR



Connector Installation Tool
P/N: CIT-1

Coax Strip Tool
P/N: CPT-6590



P/N: TSTL-3AKIT